

## **Improper care of your garment can lead to depletion of the fabric's performance levels over time.**

By following basic washing instructions, you can maintain the high quality performance of your technical apparel.



- ◆ Never use dryer sheets, or fabric softener - these clog the pores of the fabric and deplete performance
- ◆ Use a minimum amount of laundry products. Their additives can clog the fabric, inhibiting the wicking power of the fiber. We recommend using bleach free/scent free detergents.



## **Improper care of your garment can lead to depletion of the fabric's performance levels over time.**

By following basic washing instructions, you can maintain the high quality performance of your technical apparel.



- ◆ Never use dryer sheets, or fabric softener - these clog the pores of the fabric and deplete performance
- ◆ Use a minimum amount of laundry products. Their additives can clog the fabric, inhibiting the wicking power of the fiber. We recommend using bleach free/scent free detergents.

