

Improper care of your garment can lead to depletion of the fabric's performance levels over time.

By following basic washing instructions, you can maintain the high quality performance of your technical apparel.



- ◆ Never use dryer sheets, or fabric softener - these clog the pores of the fabric and deplete performance
- ◆ Use a minimum amount of laundry products. Their additives can clog the fabric, inhibiting the wicking power of the fiber. We recommend using bleach free/scent free detergents.



Improper care of your garment can lead to depletion of the fabric's performance levels over time.

By following basic washing instructions, you can maintain the high quality performance of your technical apparel.



- ◆ Never use dryer sheets, or fabric softener - these clog the pores of the fabric and deplete performance
- ◆ Use a minimum amount of laundry products. Their additives can clog the fabric, inhibiting the wicking power of the fiber. We recommend using bleach free/scent free detergents.

